


This PDF is available at <http://nap.edu/18920>

SHARE



## The October 1985 Landslide at Barrio Mameyes, Ponce, Puerto Rico

### DETAILS

21 pages | 8.5 x 11 | PAPERBACK

ISBN 978-0-309-31125-0 | DOI 10.17226/18920

### CONTRIBUTORS

Silva-Tulla, Francisco; Committee on Natural Disasters; Commission on Engineering and Technical Systems; National Research Council

GET THIS BOOK

FIND RELATED TITLES

Visit the National Academies Press at [NAP.edu](http://NAP.edu) and login or register to get:

- Access to free PDF downloads of thousands of scientific reports
- 10% off the price of print titles
- Email or social media notifications of new titles related to your interests
- Special offers and discounts



Distribution, posting, or copying of this PDF is strictly prohibited without written permission of the National Academies Press. ([Request Permission](#)) Unless otherwise indicated, all materials in this PDF are copyrighted by the National Academy of Sciences.

Copyright © National Academy of Sciences. All rights reserved.

# The October 1985 Landslide at Barrio Mameyes, Ponce, Puerto Rico

*Prepared by:*

Francisco Silva-Tulla, Consulting Engineer, Geotechnics  
12 Baskin Road, Lexington, Massachusetts

*For:*

Committee on Natural Disasters  
Commission on Engineering and Technical Systems  
National Research Council

PROPERTY OF  
NAS-NAE  
LIBRARY

NATIONAL ACADEMY PRESS  
Washington, D.C. 1986

Order from  
National Technical  
Information Service  
Springfield, Va.  
22161  
Order No. PB88-114317

OE  
599  
112  
K9  
238  
1936  
0.1

**NOTICE:** The Committee on Natural Disasters project, under which this report was prepared, was approved by the Governing Board of the National Research Council, whose members are drawn from the councils of the National Academy of Sciences, the National Academy of Engineering, and the Institute of Medicine. The members of the committee responsible for the report were chosen for their special competences and with regard for appropriate balance.

This report has been reviewed by a group other than the authors according to procedures approved by a Report Review Committee consisting of members of the National Academy of Sciences, the National Academy of Engineering, and the Institute of Medicine.

The National Research Council was established by the National Academy of Sciences in 1916 to associate the broad community of science and technology with the Academy's purposes of furthering knowledge and of advising the federal government. The Council operates in accordance with general policies determined by the Academy under the authority of its congressional charter of 1863, which establishes the Academy as a private, nonprofit, self-governing membership corporation. The Council has become the principal operating agency of both the National Academy of Sciences and the National Academy of Engineering in the conduct of their services to the government, the public, and the scientific and engineering communities. It is administered jointly by both Academies and the Institute of Medicine. The National Academy of Engineering and the Institute of Medicine were established in 1964 and 1970, respectively, under the charter of the National Academy of Sciences.

This study was supported by the Federal Emergency Management Agency, the National Oceanic and Atmospheric Administration, and the National Science Foundation under NSF Grant No. ECE-8513685 to the National Academy of Sciences. Any opinions, findings, and conclusions or recommendations expressed in this report are the author's and do not necessarily reflect the views of the sponsoring agencies or the National Research Council.

A limited number of copies of this report are available from:

Committee on Natural Disasters  
National Academy of Sciences  
2101 Constitution Avenue, N.W.  
Washington, D.C. 20418

Also available from:

National Technical Information Service  
Attention: Document Sales  
5285 Port Royal Road  
Springfield, Virginia 22161

Report No: CETS-CEE-034  
Price Codes: paper A02, mf A01

Printed in the United States of America

COMMITTEE ON NATURAL DISASTERS (1985)

**Chairman**

**METE A. SOZEN (Earthquake Engineering), University of Illinois, Urbana**

**Immediate Past Chairman**

**KISHOR C. MEHTA (Wind Engineering), Institute for Disaster Research,  
Texas Tech University, Lubbock**

**Members**

**ARTHUR N. L. CHIU (Wind Engineering), Department of Civil Engineering,  
University of Hawaii at Manoa**

**ROBERT G. DEAN (Coastal Engineering), Department of Coastal and  
Oceanographic Engineering, University of Florida, Gainesville**

**JOHN A. DRACUP (Hydrology), Civil Engineering Department, University of  
California, Los Angeles**

**JOSEPH GOLDEN (Meteorology), National Weather Service, National Oceanic  
and Atmospheric Administration, Silver Spring, Maryland**

**T. WILLIAM LAMBE (Geotechnical Engineering), Consultant, Longboat Key,  
Florida**

**DENNIS S. MILETI (Sociology), Department of Sociology, Colorado State  
University, Fort Collins**

**JAMES K. MITCHELL (Social Sciences), Department of Geography, Rutgers  
University, New Brunswick, New Jersey**

**JOSEPH PENZIEN (Earthquake Engineering), Department of Civil Engineering,  
University of California, Berkeley**

**WILLIAM J. PETAK (Systems Engineering), Institute of Safety and Systems  
Management, University of Southern California, University Park, Los  
Angeles**

**LESLIE E. ROBERTSON (Wind Engineering), Robertson, Fowler & Associates,  
New York, New York**

**RANDALL G. UPDIKE (Geological Engineering), Alaska Division of Geological  
and Geophysical Surveys, Anchorage,**

## **Staff**

**RILEY M. CHUNG, Committee Director**  
**STEVE OLSON, Consultant Editor**  
**BARBARA RICE, Consultant Editor**  
**LALLY ANNE ANDERSON, Secretary**

## **Liaison Representatives**

**WILLIAM A. ANDERSON, Program Director, Earthquake Systems Integration,  
Division of Emerging and Critical Engineering Systems, National  
Science Foundation, Washington, D.C.**

**ELEONORA SABADELL, Program Director, Division of Emerging and Critical  
Systems, National Science Foundation, Washington, D.C.**

**RICHARD J. HEUWINKEL, Senior Policy Analyst, Office of Policy and  
Planning, National Oceanic and Atmospheric Administration,  
Washington, D.C.**

**ARTHUR J. ZEIZEL, Office of Natural and Technological Hazards  
Programs, State and Local Programs and Support, Federal Emergency  
Management Agency, Washington, D.C.**

**LAWRENCE W. ZENSINGER (Alternate), Chief, Office of Disaster Assistance  
Programs, State and Local Programs and Support, Federal Emergency  
Management Agency, Washington, D.C.**

## **CONTENTS**

<b>Introduction</b>	<b>1</b>
<b>The Mameyes Landslide</b>	<b>1</b>
<b>Slide Geometry</b>	<b>2</b>
<b>Shear Strength</b>	<b>4</b>
<b>Pore Pressures</b>	<b>5</b>
<b>Recommendations</b>	<b>7</b>
<b>Appendix: Tasks for Mameyes Landslide Investigation</b>	<b>8</b>
<b>National Research Council Reports of Postdisaster Studies, 1964-1986</b>	<b>11</b>

## **ACKNOWLEDGMENTS**

**The U.S. Army Corps of Engineers coordinated access to the landslide area, providing off-road vehicle transportation and arranging use of a National Guard helicopter. The assistance of LTC Stanley G. Phernambucq, James W. Erwing, W. F. Marcuson III, Roberto Lluch, Jose M. Rosado, and Ernestina Miranda was particularly helpful.**

THE OCTOBER 1985 LANDSLIDE AT  
BARRIO MAMEYES, PONCE, PUERTO RICO

INTRODUCTION

During the early hours of the morning on Monday, October 7, 1985, a landslide destroyed a large section of the Mameyes neighborhood in Ponce, Puerto Rico. On Saturday, October 12, the Committee on Natural Disasters requested that the author visit Ponce to assess the need for an in-depth technical study of the landslide. The author arrived in Puerto Rico on October 13 and spent the following two days in the landslide area.

This report summarizes observations made at Mameyes, outlines tasks for an engineering study of the landslide, and strongly recommends actions to assess the safety of other heavily populated slopes in the area.

THE MAMEYES LANDSLIDE

The landslide occurred during an intense storm that developed into Hurricane Isabel after moving away from the Puerto Rico area. According to the San Juan Office of the National Weather Service, the storm produced the heaviest precipitation in Puerto Rico since 1899. A record rainfall of 18.20 in. was recorded between 8:00 a.m. on Sunday, October 6, and 8:00 a.m. on Monday, October 7, the day the landslide occurred. In addition to the Mameyes landslide, the rainfall caused extensive flooding throughout the island.



The slope apparently failed around 4:30 a.m. and moved in sections.\* According to USGS geologist Russell H. Campbell, there were three to four segments of movement over a 1/2- to 1-hour period. According to witness accounts reported by the U.S. Army Corps of Engineers, the slope failed in five separate segments.

The Mameyes landslide destroyed or damaged over 200 houses. Estimates of lives lost range from 130 to 500.


### SLIDE GEOMETRY

Figures 1 through 3 show aerial views of the Mameyes landslide. The roughly triangular slide covers an area of about 25,000 m<sup>2</sup> (the base of the triangle equals approximately 190 m and the height of the triangle equals approximately 230 m, measured from a 1:1,000 aerial photograph displayed at the disaster operations center). The subsoil consists of weathered Juana Diaz formation, a calcareous sandstone overlain by chalky limestone, with bedding planes striking N 87 W and dipping 20 SW. Before the slide, the ground surface sloped 20 to 25 degrees in the general direction of the bedding planes' dip. Two intersecting joint sets with a nearly vertical dip and strikes of N 63 E and N 60 W define the head of the slide (the apex of the triangle). The scarp at the head of the slide varies in height from 5 to 10 m. A relatively intact soil block dominates the center of the slide area. Slide debris surrounds this soil block, which moved downslope about 30 m. Near the toe of the landslide, debris 10 to 12 m deep accumulated over a reinforced concrete box culvert through which La Colectora Creek flows. The culvert apparently remained functional after the landslide.

The local and national press referred to the Mameyes disaster as a mud flow or an avalanche. However, field inspection indicates that Mameyes experienced a wedge-type landslide explainable by soil and rock mechanics principles. Determination of the slide geometry, pore pressures, and strengths acting at failure will require additional investigation.

---

\*U.S. Army Corps of Engineers rescue teams found two electric clocks in the rubble. One had stopped at 3:00 a.m. and the other at 4:50 a.m.



**FIGURE 1 Aerial view of Mameyes landslide.**



**FIGURE 2 Toe of landslide.**




FIGURE 3 Head of Landslide.

An inspection of the area from a helicopter revealed other slopes that are densely built with houses and appear similar to the slope on which the Mameyes landslide occurred. Figure 4 shows a 140-m-wide active landslide detected behind the Las Terrazas public housing development. The landslide exits the slope 15 m above the ground floor elevation of a four-story building located less than 12 m from the toe of the slope.

#### SHEAR STRENGTH

The high vertical scarp at the head of the Mameyes slide suggests that the weathered rock at this location cracked along joint planes and probably contributed little resistance to the sliding mass. The shear strength of the material along the sliding surface undoubtedly played an important role in controlling the landslide. The slide could have occurred along a "clean" bedding plane or, more probably, along a clay



**FIGURE 4 Active landslide above Las Terrazas housing development.**

layer like the one shown in Figure 5. This 8-cm-thick layer contained a stiff, fissured, plastic clay. Similar clays frequently sustain large changes in effective stress upon wetting (pore pressures change from highly negative to zero or positive) and experience strain softening. At other locations in the landslide area, boulder-size clay pockets existed and joints and bedding planes contained thin clay deposits.

#### **PORE PRESSURES**

Almost certainly, high positive pore pressures existed along the failure surface at the time of failure. Sources of these positive pore pressures include:

1. Rainfall National Weather Service records indicate that Ponce received 18.20 in. of rain between 8:00 a.m. Sunday and 8:00 a.m. Monday



FIGURE 5 Stiff, fissured, plastic clay layer (8 cm thick).

and a total of 22.08 in. for the week ending Friday, October 11, 1985.

2. Seepage from Domestic Sewage According to persons familiar with the neighborhood, dwellings with indoor plumbing discharged sewage to cesspools built beneath the houses. Other houses used outdoor latrines. Showers and sinks commonly drained directly onto the surface of the ground.

3. Leaks from Pipes A pressurized 8-in. cast iron water pipe traversed the area near the head of the slide. Rust stains near the joints suggest that small leaks existed before the slide. Upon rupturing, the pipeline emptied a nearby 1-million-gallon water tank into the landslide area. Numerous small-diameter galvanized steel pipes supplied water to the houses. Many of these pipes showed signs of improper installation (e.g., not buried, susceptible to traffic damage, haphazard connections).

The numerous discontinuities in the weathered rock mass provided the water easy access to the failure plane. One week after the landslide, water continued to seep out near the toe of the slide.

## RECOMMENDATIONS

The author recommends that a detailed investigation of the Mameyes landslide be made, and very strongly recommends that a geotechnical safety program be undertaken for other densely populated slopes in the Ponce area.

The investigation of the Mameyes landslide should focus on determining the mechanism of failure, including the failure sequence, geometry, strength, and pore pressures. Determining the failure sequence requires prompt systematic collection and analysis of perishable data. The appendix lists some of the tasks required for the investigation.

A study of the Mameyes landslide should provide an understanding of the events and conditions leading to the disaster. More important, a thorough analysis of the landslide constitutes the logical first step toward assessing the safety of similar nearby areas.

The geotechnical safety program should seek to predict and prevent similar landslides. The program should include establishment of performance criteria, a safety assessment of potentially unstable slopes, field instrumentation and field surveillance, periodic performance evaluations, design and construction of remedial measures (if needed), and development of contingency plans. The program should also seek to provide the Commonwealth of Puerto Rico with a sound technical basis to regulate development on potentially unstable slopes.

**APPENDIX:**  
**TASKS FOR MAMEYES LANDSLIDE INVESTIGATION**

**FAILURE SEQUENCE**

1. Compile and analyze accounts of survivors
2. Study aerial photographs
3. Survey and map slide area
4. Plot movement vectors
5. Collect promptly and analyze perishable data
  - a. Clocks
  - b. Breakage patterns for pipes and power lines
6. Review records of water pumping station (pressure records for 8-in. line)
7. Monitor postfailure movements
8. Review seismograph records

**GEOMETRY**

1. Determine original topography
  - a. Use aerial photographs to delineate surface features or landslide areas
  - b. Include drainage patterns from extreme rainfall and any natural channels feeding into the landslide area.
2. Determine subsurface geometry
  - a. Study existing borings (e.g., water tank, apartment buildings)

9

- b. Make new borings near landslide (continuous sampling to detect thin clay layers)
  - c. Undertake geologic mapping of weathered rock formation and potential failure surfaces
- 3. Locate failure surface
  - a. Make exploratory borings in slide area (continuous sampling) and make use of inclinometers
  - b. Sink exploratory pits at selected locations
    - o Attempt to measure strike and dip of failure surface
    - o Sample material on failure surface

PORE PRESSURES

- 1. Measure pore pressures in failure plane
  - a. Install piezometers in borings used to determine location of failure surface
  - b. Use shortest collection zone possible
- 2. Measure pore pressures in areas adjacent to slide
  - a. Measure pore pressures just on top of failure plane
  - b. Measure pore pressures at several locations along slope cross section (e.g., head, middle, toe)
  - c. Measure negative pore pressures in clay layers away from developed areas
  - d. Install piezometers in borings used to determine soil profile

SHEAR STRENGTH

- 1. Sample materials along failure surface (during field exploration to determine location of failure surface)
- 2. Sample materials found on failure surface from areas adjacent to slide (during field exploration to determine prefailure subsoil geometry)
- 3. Perform direct shear tests to determine peak and residual shear strength of clay



10

- a. Perform tests at stress levels similar to those existing in the field
- b. Determine strain rate required for dissipation of excess pore pressures during shear
- c. Check failure plane in shear box with potential failure plane in the field
- d. Measure strength on sample from failure plane if possible

ANALYSIS

1. Select method of analysis compatible with failure mechanism (failure sequence, failure geometry, strengths, pore pressures)
2. Estimate pore pressure required for incipient instability of the Mameyes landslide

NATIONAL RESEARCH COUNCIL REPORTS OF POSTDISASTER STUDIES, 1964-1986

Copies available from sources given in footnotes a, b, and c.

EARTHQUAKES

The Great Alaska Earthquake of 1964:<sup>a</sup>

Biology, 0-309-01604-5/1971, 287 pp.  
Engineering, 0-309-01606-1/1973, 1198 pp.  
Geology, 0-309-01601-0/1971, 834 pp.  
Human Ecology, 0-309-01607-X/1970, 510 pp.  
Hydrology, 0-309-01603-7/1968, 446 pp.  
Oceanography and Coastal Engineering, 0-309-01605-3/1972, 556 pp.  
Seismology and Geodesy, 0-309-01602-9/1972, 598 pp.,  
PB 212 981.<sup>a,c</sup>  
Summary and Recommendations, 0-309-01608-8/1973, 291 pp.

Engineering Report on the Caracas Earthquake of 29 July 1967 (1968) by  
M. A. Sozen, P. C. Jennings, R. B. Matthiesen, G. W. Housner, and N. M.  
Newmark, 233 pp., PB 180 548.<sup>c</sup>

The Western Sicily Earthquake of 1968 (1969) by J. Eugene Haas and  
Robert S. Ayre, 70 pp., PB 188 475.<sup>c</sup>

The Gediz, Turkey, Earthquake of 1970 (1970) by Joseph Penzien and  
Robert D. Hanson, 88 pp., PB 193 919.<sup>b,c</sup>

Destructive Earthquakes in Burdur and Bingöl, Turkey, May 1971 (1975) by  
W. O. Keightley, 89 pp., PB 82 224 007 (A05).<sup>b,c</sup>

<sup>a</sup>National Academy Press, 2101 Constitution Avenue, N.W., Washington,  
D.C. 20418.

<sup>b</sup>Committee on Natural Disasters, National Academy of Sciences, 2101  
Constitution Avenue, N.W., Washington, D.C. 20418.

<sup>c</sup>National Technical Information Service, 5285 Port Royal Road,  
Springfield, Virginia 22161.

The San Fernando Earthquake of February 9, 1971 (1971) by a Joint Panel on the San Fernando Earthquake, Clarence Allen, Chairman, 31 pp., PB 82 224 262 (A03).<sup>b,c</sup>

The Engineering Aspects of the QIR Earthquake of April 10, 1972, in Southern Iran (1973) by R. Razani and K. L. Lee, 160 pp., PB 223 599.<sup>c</sup>

Engineering Report on the Managua Earthquake of 23 December 1972 (1975) by M. A. Sozen and R. B. Matthiesen, 122 pp., PB 293 557 (A06).<sup>b,c</sup>

The Honomu, Hawaii, Earthquake (1977) by N. Nielson, A. Furumoto, W. Lum, and B. Morrill, 95 pp., PB 293 025 (A05).<sup>c</sup>

Engineering Report on the Muradiye-Caldiran, Turkey, Earthquake of 24 November 1976 (1978) by P. Gulkan, A. Gulpinar, M. Celebi, E. Arpat, and S. Gencoglu, 67 pp., PB 82 225 020 (A04).<sup>b,c</sup>

Earthquake in Romania, March 4, 1977, An Engineering Report, National Research Council and Earthquake Engineering Research Institute (1980) by Glen V. Berg, Bruce A. Bolt, Mete A. Sozen, and Christopher Rojahn, 39 pp., PB 82 163 114 (A04).<sup>b,c</sup>

El-Asnam, Algeria, Earthquake of October 10, 1980, A Reconnaissance and Engineering Report, National Research Council and Earthquake Engineering Research Institute (1983) by Vitelmo Bertero, Haresh Shah, et al., 195 pp., PB 85 110 740 (A11).<sup>b,c</sup>

Earthquake in Campania-Basilicata, Italy, November 23, 1980, A Reconnaissance Report, National Research Council and Earthquake Engineering Research Institute (1981) by James L. Stratta, Luis E. Escalante, Ellis L. Krinitzsky, and Ugo Morelli, 100 pp., PB 82 162 967 (A06).<sup>b,c</sup>

The Central Greece Earthquakes of February-March 1981, A Reconnaissance and Engineering Report, National Research Council and Earthquake Engineering Research Institute (1982) by Panayotis G. Carydis, Norman R. Tilford, James O. Jirsa, and Gregg E. Brandow, 160 pp., PB 83 171 199 (A08).<sup>b,c</sup>

The Japan Sea Central Region Tsunami of May 26, 1983, A Reconnaissance Report (1984) by Li-San Hwang and Joseph Hammack, 19 pp., PB 84 194 703 (A03).<sup>b,c</sup>

## FLOODS

Flood of July 1976 in Big Thompson Canyon, Colorado (1978) by D. Simons, J. Nelson, E. Reiter, and R. Barkau, 96 pp., PB 82 223 959 (A05).<sup>b,c</sup>

Storms, Floods, and Debris Flows in Southern California and Arizona--1978 and 1980, Proceedings of a Symposium, September 17-18, 1980, National Research Council and California Institute of Technology (1982) by Norman H. Brooks et al., 487 pp., PB 82 224 239 (A21).<sup>c</sup>

Storms, Floods, and Debris Flows in Southern California and Arizona--1978 and 1980, Overview and Summary of a Symposium, September 17-18, 1980, National Research Council and California Institute of Technology (1982) by Norman H. Brooks, 47 pp., PB 82 224 221 (A04).<sup>b,c</sup>

The Austin, Texas, Flood of May 24-25, 1981 (1982) by Walter L. Moore, Earl Cook, Robert S. Gooch, and Carl F. Nordin, Jr., 54 pp., PB 83 139 352 (A04).<sup>b,c</sup>

Debris Flows, Landslides, and Floods in the San Francisco Bay Region, January 1982, Overview and Summary of a Conference Held at Stanford University, August 23-26, 1982, National Research Council and U.S. Geological Survey (1984) by William M. Brown III, Nicholas Sitar, Thomas F. Saarinen, and Martha Blair, 83 pp., PB 84 194 737 (A05).<sup>c</sup>

California Coastal Erosion and Storm Damage During the Winter of 1982-83 (1984) by Robert G. Dean, George A. Armstrong, and Nicholas Sitar, 74 pp., PB 85 121 705 (A05).<sup>b,c</sup>

The Tucson, Arizona, Flood of October 1983 (1984) by Thomas F. Saarinen, Victor R. Baker, Robert Durrenberger, and Thomas Maddock, Jr., 112 pp., PB 85 150 597.<sup>b,c</sup>

#### DAM FAILURES

Failure of Dam No. 3 on the Middle Fork of Buffalo Creek Near Saunders, West Virginia, on February 26, 1972 (1972) by R. Seals, W. Marr, Jr., and T. W. Lambe, 33 pp., PB 82 223 918 (A03).<sup>b,c</sup>

Reconnaissance Report on the Failure of Kelly Barnes Lake Dam, Toccoa Falls, Georgia (1978) by G. Sowers, 22 pp., PB 82 223 975 (A02).<sup>b,c</sup>

#### LANDSLIDES

Landslide of April 25, 1974, on the Mantaro River, Peru (1975) by Kenneth L. Lee and J. M. Duncan, 79 pp., PB 297 287 (A05).<sup>b,c</sup>

The Landslide at Tuve, Near Goteborg, Sweden on November 30, 1977 (1980) by J. M. Duncan, G. Lefebvre, and P. Lade, 25 pp., PB 82 233 693 (A03).<sup>c</sup>

The Utah Landslides, Debris Flows, and Floods of May and June 1983 (1984) by Loren R. Anderson, Jeffrey R. Keaton, Thomas Saarinen, and Wade G. Wells II, 96 pp., PB 85 111 938 (A06).<sup>b,c</sup>

## TORNADOES

Lubbock Storm of May 11, 1970 (1970) by J. Neils Thompson, Ernest W. Kiesling, Joseph L. Goldman, Kishor C. Mehta, John Wittman, Jr., and Franklin B. Johnson, 81 pp., PB 198 377.<sup>c</sup>

Engineering Aspects of the Tornadoes of April 3-4, 1974 (1975) by K. Mehta, J. Minor, J. McDonald, B. Manning, J. Abernathy, and U. Koehler, 124 pp., PB 252 419.<sup>c</sup>

The Kalamazoo Tornado of May 13, 1980 (1981) by Kishor C. Mehta, James R. McDonald, Richard D. Marshall, James J. Abernathy, and Daryl Boggs, 54 pp., PB 82 162 454 (A04).<sup>b,c</sup>

Building Damage in South Carolina Caused by the Tornadoes of March 28, 1984 (1985) by Peter R. Sparks, 46 pp., PB 85 204 469/AS (A04).<sup>b,c</sup>

The Los Angeles, California Tornado of March 1, 1983 (1985) by Gary C. Hart, Luis E. Escalante, William J. Petak, Clarkson W. Pinkham, Earl Schwarts, and Morton G. Wurtele, 44 pp.,<sup>b,c</sup>

## HURRICANES

Hurricane Iwa, Hawaii, November 23, 1982 (1983) by Arthur N. L. Chiu, Luis E. Escalante, J. Kenneth Mitchell, Dale C. Perry, Thomas Schroeder, and Todd Walton, 129 pp., PB 84 119 254 (A07).<sup>c</sup>

Hurricane Alicia, Galveston and Houston, Texas, August 17-18, 1983 (1984) by Rudolph P. Savage, Jay Baker, Joseph H. Golden, Ahsan Kareem, and Billy R. Manning, 158 pp., PB 84 237 056 (A08).<sup>c</sup>

Hurricanes Iwa, Alicia, and Diana--Common Themes (1985) Committee on Natural Disasters, National Research Council, 30 pp., PB 85 218 220/AS.<sup>b,c</sup>

Hurricane Diana, North Carolina, September 10-14, 1984 (1986) by James K. Mitchell, Ahmed M. Abdel-Ghaffar, Peter R. Sparks, 108 pp.<sup>b,c</sup>